

PHOENIXENGINE.COM ®
PHOENIX ENGINE REBUILDERS®

21632 N. 7th Ave, Suite 1
Phoenix AZ 85027
(602) 866-8044

ENGINE NUMBER: _____

DATE: _____

CLOCKING THE ENGINE

If your engine is going to sit for more than 6 months, it is highly recommended that you turn the engine one quarter of a turn every two to three months, so that the engine is not sitting in the same position for an extended period of time.

This keep the lifters and springs from staying in the same position for too long; also so the lifters do not stick or collapse.

This is known as clocking of the engine.

For example, 12 to 3 is one quarter turn, as demonstrated on the clock below:

